


Throttle Pedal

WIRING HARNESS-SIDE CONNECTOR



Throttle Pedal

A Sensor 2 + 5v

B Sensor 2 Ground

C Sensor 2 Signal


D Sensor 1 + 5V

E Sensor 1 Ground

F Sensor 1 Signal

Throttle Body

WIRING HARNESS-SIDE CONNECTOR



Throttle Body

A Motor drive +

B Motor Drive -

C Both sensors Ground

D Sensor 2 Signal

E Both sensors +5v

F Sensor 1 Signal